

SERVICE REPORT

DATE 2-9-23

ARRIVAL TIME 7:30

DEPARTURE TIME 12:00

JOB/TCK. NO. 193819

CSS87316

JOB NAME/LOCATION *USARC - Rainelle WV034*

SERVICE REQUESTED 4 Wall PTAC's in the training building are not operating. Need verification if they can be fixed-- please confirm

Manufacture: <u>Amana</u>				
Model#: <u>PTAC</u>				
Serial#: <u>Rooms 100, 101, and 102</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Went to the front offices. Then went to the room i knew that the unit was bad but went a head and hooked up my service tool and tried running unit in test mode but the unit would not run. Packed up tools and went to room 101 or data room and took the cover off unit. Tested power and then pulled board out to hook up service tool and then ran in test mode everything work but the actuator for the hot water valve. Pack up tools and then went to OMS shop because they were laying carpet in room 100. Once they were done i went in and took cover off and then hooked up service tools and ran unit in test mode and everything came on and unit checked out good. Told client i was done and then went done paperwork.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE W. J. [Signature]

Customer Representative