



Location: Johnstown ANG Date: 4/23/19 Insp. by: CR/RR

Hangar# _____ Bldg# 292 Delays _____

ITEM	Good	Fair	Replace	Notes
1. Drive Motor	✓			Need to Replace Geabox Fluids
2. Trans/Brake	✓			
3. Chain	✓			
4. Sprockets	✓			
5. Shear Pins	✓			
6. Lead Dr Wheel	✓			
7. Trail Dr Wheel	✓			
8. Non Drive Wheel	✓			
9. Push Buttons	✓			
10. Personnel Door	✓			
11. Pers Door Limit	✓			
12. Open Limit	✓			
13. Close Limit	✓			
14. S.O. Cord				Bus Rail is in good condition
15. Cable System				N/A
16. Upper Rollers	✓			
17. Upper Track	✓			
18. Lower Track	✓			
19. Vertical W/S	✓			
20. Horizontal W/S	✓			
21. Sheet Metal	✓			
22. Warn. Devices			✓	Not working on doors #2, 3, 3A+4A
23. Electrical	✓			

Additional Comments:

National Door Service

Fabric Hangar Door Inspection Check List

Location: Johnstown ANG Date: 4/23/19 Insp. By: CR/RR
 Hangar # _____ Bldg# 288 Delays: _____
 Fabric Door Manufacture: Megadoor - 4 doors total

Item:	Good	Fair	Replace	Notes
1. Top Beam	✓			
2. Motors/Drums	✓			
3. Straps/Cables	✓			
4. Limits	✓			
5. Arresters/Rollers	✓			
6. Track guides/Rollers	✓			
7. Track /Wind locks	✓			
8. Bottom Beam	✓			
9. Fabric		✓		outside worn / interior good
10. Retainer	✓			
11. Guide Grommets	✓			
12. Weather Seal	✓			
13. Push Buttons	✓			
14. Electrical	✓			
15. Mullions	✓			

Additional Comments: All 4 doors are in good working order.