



4504

Energy Management Technologies, LLC

Service 518-631-6004 Main 518-783-7810 Fax 518-783-2079

FIELD REPORT

Rotterdam
 Location Name / Address
Schenectady Army
 Contact / Phone

 Bill To
CMI

Date

8-20-19

Service Contract #

Installed Contract #

Technician Code

 Contract T & M Quoted Warranty Sales Support Material Sale Only

Problem Description:

CS #19948

JOBSITE SAFETY CHECKLIST

- Electrical Shock Hazards
- Confined Space
- Inadequate Ventilation
- Water/Oil/Other Liquids on Floor
- Trip or Fall Hazards
- Fire or Explosive Hazards
- Site Checked

WORK PERFORMED

*Find blower motor @ AHU (above Eric office)
 Bad. New motor on order*

*Take apart unit to get the blower motor out,
 install new blower motor, rotation correct,
 Amp @ 4.0. goes alarm*

REFRIGERANT ACTIVITY

Did Refrigerant Activity occur?

- Yes If yes, a Refrigerant Activity
- No Report Must be completed

SERVICE EXPENSE

PARTS and MATERIAL

PARTS, MATERIAL SOURCE	Source	Qty	Part #	Description	PO #
<input type="checkbox"/> CS Customer Supplied	UP	1	Blower motor		
<input type="checkbox"/> PC Procurement/Cash					
<input type="checkbox"/> TS Truck					
<input type="checkbox"/> TP EMTech Parts					
<input type="checkbox"/> VP Vendor Purchase					

EXPENSE TYPE
(CHECK ALL THAT APPLY)

- Sm Recovery Sys
- Lg Recovery Sys
- Vacuum Pump
- Welder
- Tube Brush Unit
- Technology Charge
- Fuel Charge
- Environment Fee
- Trip Charge
- Pressure Washer
- Mileage
- Misc. Supplies

LABOR

Date	Name	DDC (Tech)	MS (Mech)	Reg/Other Time	Over Time	Double Time
8-20-19	Mile			3.5		
8-23-19	Mile			3		

Follow-up Required? Yes No Describe

Customer Signature

Date

PO #