⚛ EMTech

4816

Energy Management Technologies, LLC
Service 518-631-6004   Main 518-783-7810   Fax 518-783-2079

FIELD REPORT

Location Name / Address	Bill To		Date
Saugerties Army Reserve CMI			11/7/19
Contact / Phone	Service Contract #	Installed Contract #	
CSS #22413	19801		
	Technician Code		
	☐ Contract ☒ T & M ☐ Quoted ☐ Warranty ☐ Sales Support ☐ Material Sale Only		

Problem Description: Boilers not enabled

JOBSITE SAFETY CHECKLIST	WORK PERFORMED
☐ Electrical Shock Hazards	Found boiler not enabled due to shutdown
☐ Confined Space	push button outside boiler room
☐ Inadequate Ventilation	HWP-3 off at MCC reset & found bearings going bad
☐ Water/Oil/Other Liquids on Floor	in motor Peter advises provide price to CMI
☐ Trip or Fall Hazards	
☐ Fire or Explosive Hazards	
☐ Site Checked	

REFRIGERANT ACTIVITY

Did Refrigerant Activity occur?

☐ Yes   If yes, a Refrigerant Activity
☐ No   Report Must be completed

SERVICE EXPENSE

PARTS, MATERIAL SOURCE

☐ CS Customer Supplied
☐ PC Procurement/Cash
☐ TS Truck
☐ TP EMTech Parts
☐ VP Vendor Purchase

PARTS and MATERIAL

Source	Qty	Part #	Description	PO #

EXPENSE TYPE (CHECK ALL THAT APPLY)

☐ Sm Recovery Sys
☐ Lg Recovery Sys
☐ Vacuum Pump
☐ Welder
☐ Tube Brush Unit
☐ Technology Charge
☐ Fuel Charge
☐ Environment Fee
☐ Trip Charge
☐ Pressure Washer
☒ Mileage
☒ Misc. Supplies

LABOR

Date	Name	DDC (Tech)	MS (Mech)	Reg/Other Time	Over Time	Double Time
11/7/19	David Ogden		X	3		

Follow-up Required?   ☐ Yes   ☐ No   Describe

Customer Signature		Date	PO #

White - EMTech   Yellow - Processing   Pink - Customer

Services described were performed as part of the terms of this document

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: **Saugerties Army Reserve**   Date of Visit: **11/7/19**

Contractor Personnel on Site:

1. Dave Ogden   4. _____
2. _____   5. _____
3. _____   6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. _____
2. _____
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls – Service Call Number and Description

1. CSS# 22413- No Heat in Building
2. _____
3. _____

Over and Above Repair Work – Order Number and Description of Work Completed

Found Boiler not enabled due to
shutdown.
Pushed Button outside.
HWP-3 off @ MCC - reset i found
bearings going bad.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Dave Ogden   Date: 11/7/19

Signed: Dave Ogden

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Michael Moseman   Date: 11-7-2019

Signed: michael moseman

E-Mail: michael.moseman.ctr@mail.mil