

ASSE International

Double Check Backflow Prevention Assembly (DC)
ASSE Standard #1015 Field Test Report

Owner of Property PA027 ARMY RESERVE CENTER

Address 950 NEW CASTLE RD

City FARRELL State PA Zip Code 16121

Occupant of Property (if different from owner)

Occupant Address

City _____ State _____ Zip Code _____

Manufacturer of Assembly: WATTS Model #: 007M1QT

Size of Assembly: 2" Serial #: 189117

Location of Assembly and Equipment or System Application: MAINTENANCE ROOM

DOMESTIC WATER SERVICE CONTAINMENT

Test Equipment:

Manufacturer: WATTS Model #: TK9A Serial #: 0104817

Calibration Date: 04/25/2017

Date test was performed: 03/02/2018 Time test was performed: 12:30 PM Static Line Pressure: 50 PSI

	Check Valve #1	Check Valve #2	Shutoff valve #2
Initial Test	Leaking () psid 2.0 Closed Tight (✓)	Leaking () psid 2.0 Closed Tight (✓)	Leaking () Closed Tight (✓)
Describe parts and repairs when needed			
Final Test	Leaking () psid 2.0 Closed Tight (✓)	Leaking () psid 2.0 Closed Tight (✓)	Leaking () Closed Tight (✓)

Certified Tester (print) Joseph G Benz

Address 5225 Library Road, Suite 146

City Bethel Park State PA Zip 15102

Phone #: (412)852-4966

License #: H.P. 0683 Certification # ASSE5429

Assembly Final Performance

Pass



Fail

Signature  Date: 03/02/18

Comments or Recommendations (continue to other side, if needed):