

WO #2317 Asset# 7167

ASSE International

Double Check Backflow Prevention Assembly (DC) ASSE Standard #1015 Field Test Report

Owner of Property PA063 ARMY RESERVE CENTER

Address 410 MILLER AVE.

City NEW CASTLE

State PA

Zip Code 16101

Occupant of Property (if different from owner) _____

Occupant Address _____

City _____

State _____

Zip Code _____

Manufacturer of Assembly: CONBRACO

Model #: 4010802

Size of Assembly: 2"

Serial #: I8215

Location of Assembly and Equipment or System Application: MAINTENANCE ROOM
DOMESTIC SERVICE CONTAINMENT GARAGE

Test Equipment:

Manufacturer: WATTS

Model #: TK9A

Serial #: 0104817

Calibration Date: 04/25/2017

Date test was performed: 03/02/2018 Time test was performed: 1:30 PM Static Line Pressure: 80 PSI

	Check Valve #1	Check Valve #2	Shutoff valve #2
Initial Test	Leaking () psid <u>1.6</u> Closed Tight (✓)	Leaking () psid <u>1.4</u> Closed Tight (✓)	Leaking () Closed Tight (✓)
Describe parts and repairs when needed			
Final Test	Leaking () psid <u>1.6</u> Closed Tight (✓)	Leaking () psid <u>1.4</u> Closed Tight (✓)	Leaking () Closed Tight (✓)

Certified Tester (print) Joseph G Benz

Address 5225 Library Road, Suite 146

City Bethel Park State PA Zip 15102

Phone #: (412)852-4966

License #: H.P. 0683 Certification # ASSE5429

Assembly Final
Performance

Pass ☒

Fail ☐

Signature  Date: 03/02/18

Comments or Recommendations (continue to other side, if needed): _____