

WO #2316 Asset #7166

ASSE International

Reduced Pressure Principle Backflow Preventer (RP)

ASSE Standard #1013 Field Test Report

Owner of Property 99TH RSC PA168

Address 9060 MARSHALL RD

City CRANBERRY TOWNSHIP

State PA

Zip Code 16066

Occupant of Property (if different from owner) _____

Occupant Address _____

City _____

State _____

Zip Code _____

Manufacturer of Assembly: APOLLO

Model #: RP40

Size of Assembly: 2"

Serial #: 170560

Location of Assembly and Equipment or System Application: MECHANICAL ROOM GARAGE BUILDING
DOMESTIC CONTAINMENT

Test Equipment:

Manufacturer: WATTS

Model #: TK9A

Serial #: 0104817

Calibration Date: 04/25/2017

Date test was performed: 02/28/2018 Time test was performed: 12:00 PM Static Line Pressure: 60 PSI

	Check Valve #2	Shutoff valve #2	Check Valve #1	Pressure Differential Relief Valve
Initial Test	Leaking () Closed Tight (✓)	Leaking () Closed Tight (✓)	Leaking () Closed Tight (✓) Pressure Drop Across Check Valve #1 <u>7.4</u> psid	Opened at <u>2.6</u> psid
Describe parts and repairs when needed				
Final Test	Leaking () Closed Tight (✓)	Leaking () Closed Tight (✓)	Leaking () Closed Tight (✓) Pressure Drop Across Check Valve #1 <u>7.4</u> psid	Opened at <u>2.6</u> psid

Certified Tester (print) Joseph G. Benz

Address 5225 Library Rd., Ste 146

City Bethel Park

State PA

Zip 15102

Phone #: (412)852-4966

License #: H.P. 0683

Certification # ASSE5429

Assembly Final Test Performance

Pass



Fail



Signature _____

Date: 02/28/2018

Comments or Recommendations (continue to other side, if needed): _____