

Additional Funding Request

Site: WV006	WO# 6784	CSS # 16365	Asset# NA
Description of Repairs	Need to replace both locks		
Diagnosis: Initial Work Order CSS# 16365	The locks on both Man Doors of the Marine Engineer building		
Explanation of Additional Costs for Repairs	Labor and material to replace locks		
Additional Labor Cost to Perform Repairs	$4 \times \$70 = \300.00		
Additional Material Cost to Perform Repairs	\$467.28		
Total Cost of Repair	\$767.28		

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WU004

Date of Visit: 3/25/15

Contractor Personnel on Site:

1. Isaac Pratt 2.


Work Performed:

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders -

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: ISAAC RUIT Date: 3/25/19

Signed: 

To be signed by Facility Manager:

I certify that the above-named individuals representing the Contractor arrived on site and to the

best of my knowledge, completed the stated work listed:

Print Name/Rank: Winston Bolling / CPL E-4 Date: 20140325

Signed: Winston Bolling

E-Mail: Winston.Bolling@USMC.MIL

LABOR \$75.00/Hr

4 HRS $\times \$75.00/\text{hr} = \300.00

Part Number SCL94533A626

SCHLAGE Mortise Lock Entry Function

\$306.90 our cost

20% markup = \$61.38

your cost \$368.28

REKEY 1 lock = \$15.00

3 Keys. $\times \$15.00 = \45.00

SERVICE CALL \$75.00

300.00
368.28
15.00
45.00
<hr/>
TOTAL 692.28
+ 75.00
<hr/>
TOTAL 767.28

