

Additional Funding Request

Site: WV006	WO# 6782	CSS # 16368	Asset# NA
Description of Repairs	Need to replace panic device		
Diagnosis: Initial Work Order CSS# 16368	Urgent The door hardware including the panic bar have mechanically failed		
Explanation of Additional Costs for Repairs	Labor and material to replace panic device		
Additional Labor Cost to Perform Repairs	$4 \times \$70 = \300.00		
Additional Material Cost to Perform Repairs	\$347.86		
Total Cost of Repair	\$647.86		

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV 006 Date of Visit: 3/25/19

Contractor Personnel on Site:

1. Isaac Davis 2.

Work Performed:

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders -

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: 1302c Reit Date: 3/25/17

To be signed by Facility Manager:

I certify that the above-named individuals representing the Contractor arrived on site and to the

best of my knowledge, completed the stated work listed:

Print Name/Rank: Larry Salas Date: 25 MAR

Signed: Larry Salas

E-Mail: Larry.g.Salas.mil@mail.mil

Labour \$75.00/HR

4 HRS x \$75.00 = \$300.00

300.00

Jackson Panic DEVICE
Part # JA1095RC4628

212.44

Cost \$177.38

60.00

20% Markup = \$35.48

+ 75.00

TOTAL 647.86

Hour cost \$212.44

OTHER PARTS NEEDED \$60.00

SERVICE CALL \$ 75.00

