



Garbage disposal located in facility kitchen is inoperable and in need of a life cycle replacement. Garbage disposal is used during drill weekends. Serial# N1279275 Model# SS500-30

Proposal is to replace the garbage disposal with a direct replacement.

**Scope of work:**

Prepare project site for the installation.

Furnish & Install 1 new model SS500, 5HP, 3PH Garbage Disposal

Modify & tie into existing pipe

Start up & verify proper operation

CMI Cost Estimate								
Over & Above								
WV053 Wheeling								
Garbage disposal located in facility								
CSS #14351 - CMI # 6409								
Prepared By: J. Bayne								
12.06.18								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
<b>1. Repair Cost</b>								
1.1 Labor	\$ 98.00	8						\$ 784.00
1.2 5HP Commercial Disposal/material					\$ -	\$ -	\$ -	\$ 4,533.00
5 day lead time								
1.3 Consumables								\$30.00
<b>Sub Total Repair Cost</b>								<b>\$ 5,347.00</b>
<b>2. Initial Service Call Investigation</b>								
2.1 Field Review at Site	\$ 98.00	4						\$ 392.00
CE Factor 102%								\$ 114.78
<b>Grand Total</b>								<b>\$ 5,853.78</b>