

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 3/27/18

ARRIVAL TIME 8:00 am

DEPARTURE TIME 9:30

JOBSITE NO. 149478

CUSTOMER PO. NO.

JOB NAME/LOCATION USARC, Morgantown, WV 26509

SERVICE REQUESTED Investment is labor to inspect and recertify 2 backflow preventers located at USARC Morgantown, WV029

Manufacturer: *Watts*

Model #: 909

Serial#: 270457

Refrigerant Added: Qty lb oz TYPE

Refrigerant Removed: Qty lb oz

WORK PERFORMED/UNIT INFO

Arrived at site and checked in

Main Bldg- Performed certification test on backflow preventer. Device passed test.

Motor pool bldg- could not get access to mechanical room. Will return another day.

Filled out all necessary test forms and tags for device

Checked out with Jennifer before leaving site

- Leak Tested
- Leak Found
- Leak Repaired

Method: _____

Total Charge: _____

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE

EXPLAIN another device to check

SIGNATURE

Barley

Customer Representative