



OneCIS Insurance Company

95 Oakwood Rd
Lake Zurich, IL 60047
(855) 593-5115
www.us.bureauveritas.com



May 22, 2019

44110-007209.00

Bernie Koblinsky
Johnstown USARC #2
1300 Saint Clair Rd
Johnstown, PA 15905-1411
bernie.koblinsky@cmimgmt.com

RE: Jurisdictional Inspection:
Johnstown USARC #2
1300 Saint Clair Rd
Johnstown, PA 15905-1411

Thank you for the consideration I received during my visit on April 30, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by Scott Werry of CMI 412-510-7772 during my visit.

The inspections were performed on behalf of CMI Management, Inc. (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendations
2008	Water Tube	PA-052 01	86579	See Below
2008	Water Tube	PA-052 02	86658	None
2008	Water Tube	PA-052 03	86605	See Below

The following observations were noted during the inspection of this equipment:

The following safety equipment was operationally tested satisfactorily as follows: low water fuel cut outs with manual reset, flame lock out.

As a result of this inspection, there were 3 recommendations suggested.

The OneCIS Operating Certificates are being withheld for the objects with code recommendations listed below:

The recommendations made to correct the deficiencies are listed below. Please indicate any actions taken on these recommendations, by calling me at the number listed below.

Based upon this visit, one boiler is satisfactory and two boilers need repairs. A OneCIS Operating Certificate was issued for the boiler in satisfactory condition.

The next inspection is tentatively scheduled to be completed by 04/30/2020.

This document is advisory in nature. Reports or certificates provided in connection with any state-required boiler or pressure vessel inspection do not mean that all hazards or conditions were controlled at the time of the inspection. No liability is assumed by the information contained in this document.

Recommendations

No. **2019-05-1** - Complete within 30 days
Giannoni-PA-052 01 located in Boiler room

Condition: Safety relief valve would not lift by hand.

Requirement: Repair or replace the relief valve with an ASME approved safety valve with the proper relieving pressure and capacity. In accordance with the ASME NBIC.

No. **2019-05-2** - Complete within 30 days
Giannoni-PA-052 03 located in Boiler room

Condition: The boiler display was registering a code F-13 failure which is a fan motor failure.

Requirement: Repair or replace the fan motor.

No. **2019-05-3** - Complete within 30 days
Giannoni-PA-052 03 located in Boiler room

Condition: The safety relief valve is inoperable.

Requirement: Repair or replace the safety relief valve with an ASME approved safety valve with the proper relieving pressure and capacity. In accordance with ASME NBIC.

Please contact me by phone at 724-759-9488 or by e-mail at craig.bell@onecis.com if there are any questions and to clear any recommendations.

Sincerely,

Craig Bell

Craig Bell
Boiler & Machinery Inspection Specialist

DISTRIBUTION

Cc:

Thomas Kovach, OneCIS Insurance
Thomas.kovach@onecis.com

FILE