




SENTRY MECHANICAL
1724 Leechburg Road
Pittsburgh, PA 15235
(412) 795-3040
Fax (412) 795-3206

MECHANICAL SYSTEM EVALUATION
One copy per piece of equipment

Date: 3/27/19
Customer Name: UNIT JONASTOWN
Address: 20 AVIATION DR.
Job Location: JONASTOWN
Equipment Type: HOT WATER PUMP
Model #: 2X2X7 66258F
Volts: 480
Equipment #: HWP-3
Filter(s) (qty, size & type): N/A
Bell(s) (qty, size & type): N/A
Accessibility: Good
Evaluation: MECHANICAL SEAL HAS FAILED ON GEAR SHAFT OF B&G 80 SEERS PUMP. MECHANICAL SEAL KIT WILL BE REQUIRED TO MAKE REPAIR. ISOLATION YAWES IN PLACE BEFORE AND AFTER THE PUMP. GEAR POWER REQUIRED FOR RUNNING GEAR RATE. IMPELLER CONDITION IS UNKNOWN.

Notes Attached: Yes ☐ No ☐
Priority 1-S: 3 (5 Being High)
Status: Incomplete ☒ Complete ☐
Reviewed By: GALT, J. Date: 3/27/19
Sentry Tech: J. GALT
PINK - Technician
YELLOW - JOB FILE

Asset # 4984-HWPP
HWP-3



Series 80

Today at 10:08 AM

Scott,

PN: 186862LF Seal Kit \$ 143.00 ea.
PN: P57700 Gasket \$ 4.20 ea.

Plus Freight

Stock

Thanks,

Tim Ross

Thermoflo Equipment Company, Inc.

3233 Babcock Boulevard

Pittsburgh, PA 15237

Phone: 412-366-2012

Mobile: 412-651-6018

Fax: 412-367-0842

tross@thermoflo.com

This email and any files transmitted with it may be proprietary and are intended solely for the use of the individual or entity to who they are addressed. If