

## Additional Funding Request

Submitted: 4/22/21

<b>MD066 - CHEM line is broke to the cooling tower</b>	<b>CSS #30139 WO# 14140</b>											
Description of Repairs	S&S proposes to isolate and repair broken pipe that feeds treatment to the cooling tower. Once repaired, will secure heat trace, insulation back on along with outer aluminum coverings. Will turn back on treatment and make sure it is working without issue.											
Original SC Investigative Diagnosis	<b>\$300</b>											
Diagnosis: Initial Work Order	CHEM line is broke to the cooling tower											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	<b>Materials: \$33.87</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th><th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th><th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th><th style="text-align: left; padding: 2px;"><b>TOTAL</b></th></tr> </thead> <tbody> <tr> <td style="padding: 2px;">Parts See Quote for detail</td><td style="padding: 2px; text-align: center;">1</td><td style="padding: 2px; text-align: center;">\$33.87</td><td style="padding: 2px; text-align: center;">\$33.87</td></tr> </tbody> </table>				<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	Parts See Quote for detail	1	\$33.87	\$33.87
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>									
Parts See Quote for detail	1	\$33.87	\$33.87									
Additional Labor Cost to Perform Repairs	<b>Labor: \$600</b> Plumber Labor Tech 6 hours/Rate \$100.00 per hour = \$600.00											
<b>Total Cost of Repair</b>	<b>\$933.87</b>											