

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY060 *Schenectady*

Date of Visit: 10-26-22

Contractor Personnel on Site:

1. MIC *1*
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. XJ-A
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. XJ-A
2. _____
3. _____
4. _____

Other Recurring Services

1. XJ-A
2. _____
3. _____
4. _____

Service Calls - Service Call Number and Description

1. QSS#8946, follow up SP1#10387 Replaced Filter @ water valve
2. VALVE, Replaced filter valve. Cycled unit in heat & cool - gas valve
3. _____

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY060 Se habla Espanol

Date of Visit: 10-26-22

Contractor Personnel on Site:

1. MICHAEL
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. XJ-A
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. XJ-A
2. _____
3. _____
4. _____

Other Recurring Services

1. XJ-A
2. _____
3. _____
4. _____

Service Calls – Service Call Number and Description

1. QSS# 89460 follow up #1#100387 Replaced fan motor @ water
2. VALVE, Replaced 1/2" switch. Cycled unit in heat & cool -
3. QPS XLR UNIT