



Job # 1832

[illegible]

Proposal to:

- Remove the current actuator at the condenser loop water valve for Heat pump 1-3
- Replace with a new actuator
- Test operation

8321

NOTE: MUA COST DATA ANALYSIS AND NEGOTIATION. THE LABOR HOURS IS WITHIN THE LOCAL SCA WAGE RATE FOR THE WORK DURATION PROPOSED WHICH IS TO REPLACE ACTUATOR DAMAGED OUTSIDE AIR LOUVER ASSEMBLY. THE MEANS AND METHODS PROPOSED AND THE REPAIR WORK IS TYPICAL OF WORK COMPLETED AT OTHER NY FACILITIES AND CONSIDERED FAIR AND REASONABLE.

Digitally signed by LATINI.DAVID.JAMES.1030705331
Date: 2022.05.10 14:14:53 -04'00'

ATTACHMENT J-0200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY 060 Date of Visit: 5-23-22

Contractor Personnel on Site:

- | | |
|------------------------|----------|
| 1. <u>Mike Dunsall</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

- | | |
|---------------|-------|
| 1. <u>N-A</u> | _____ |
| 2. _____ | _____ |
| 3. _____ | _____ |
| 4. _____ | _____ |

Inspection, Testing, and Certification

- | | |
|---------------|-------|
| 1. <u>N-A</u> | _____ |
| 2. _____ | _____ |
| 3. _____ | _____ |
| 4. _____ | _____ |

Other Recurring Services

- | | |
|---------------|-------|
| 1. <u>N-A</u> | _____ |
| 2. _____ | _____ |
| 3. _____ | _____ |
| 4. _____ | _____ |

Service Calls – Service Call Number and Description

- | | |
|---|-------|
| 1. <u>CSS #34317 Redacted BROKEN WATER Loop</u> | _____ |
| 2. <u>ACTUATOR @ HP 1-3, ops Normal</u> | _____ |
| 3. _____ | _____ |

ATTACHMENT J-0200000-05
FORMS

Over and Above Repair Work -- Order Number and Description of Work Completed

CS5# 34317 Replaced broken water loop Actuator
@ HP 1-3 ops Normal

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name:

Mike Dush

Date:

5-23-22

Signed:

[Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank:

Chris Pothier AFOS

Date:

5-23-22

Signed:

[Signature]

E-Mail:

christopher.n.pothier.ctr@army.mil