

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY 128

Date of Visit: 6-23-22

Contractor Personnel on Site:

1. M(6)D
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. N.A
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. N.A
2. _____
3. _____
4. _____

Other Recurring Services

1. N.A
2. _____
3. _____
4. _____

Service Calls - Service Call Number and Description

1. 055#595 - Spent two, cold (NOT locate)
2. LOCATED "BACK FLOW PREVENTER" VALVES OVER IN THE OMS
3. BYE, EACH BACK FLOW HAS A SMALL LEAK. will quote A
Replacement



Mechanical HVAC Service Contractors

AC Service Contractors
CMI Management

Phone: (518) 326-8450 • Fax: (518) 326-8435
P.O. Box 311, 95 Hudson River Road
Waterford, New York 12188

HVAC

Job # 18495

UNIT	MAKE	MODEL	SERIAL #	VOLTS	ENVIRONMENTAL CHECK LIST		
NAME	SAUGERTIES Army Reserve		NY128		CONDENSING UNIT	QTY.	TYPE/DISPOSITION
STREET			DATE	6-23-22	<input type="checkbox"/> RECOVERED		
CITY					<input type="checkbox"/> RECYCLED		
TECHNICIAN	CSS# 595		WO# 17638		<input type="checkbox"/> RECLAIMED		
DESCRIPTION OF WORK PERFORMED					<input type="checkbox"/> RETURNED		
					<input type="checkbox"/> DISPOSAL		

COOLING OUT HEATING OUT LEAK WARRANTY INSTALLATION

LOCATED BACK FLOW PREVENTER IN THE OMS BLDG,
EA BACK FLOW PREVENTER IS LEAKING BY, WILL QUOTE A REPAIR/REPLACEMENT

RECOMMENDATIONS

Chris Pellerin

6-23-22

CUSTOMER SIGNATURE

DATE