



# HVAC

Phone: (518) 326-8450 • Fax: (518) 326-8435  
P.O. Box 311, 95 Hudson River Road  
Waterford, New York 12188

Mechanical HVAC Service Contractors

Job # 18798

CMI Management

UNIT	MAKE	MODEL	SERIAL #	VOLTS	ENVIRONMENTAL CHECK LIST		
NAME <u>Schaesetady Army</u>					CONDENSING UNIT	QTY.	TYPE/DISPOSITION
STREET			DATE <u>8-8-22</u>		<input type="checkbox"/> RECOVERED		
CITY					<input type="checkbox"/> RECYCLED		
TECHNICIAN <u>CSS # <del>15798</del> 18916</u>					<input type="checkbox"/> RECLAIMED		
DESCRIPTION OF WORK PERFORMED					<input type="checkbox"/> RETURNED		
					<input type="checkbox"/> DISPOSAL		

☐ COOLING OUT ☐ HEATING OUT ☐ LEAK ☐ WARRANTY ☐ INSTALLATION

HP-2-24 found UNIT WITH BAD FAN MOTOR.

HP-2-23 found UNIT WITH BAD FAN MOTOR

HP-2-19 UNIT WITH ECM MOTOR, ECM PROCESSOR BOARD is flashing <sup>LED</sup> code.

RECOMMENDATIONS

QTY.	MATERIALS & SERVICES	UNIT PRICE	AMOUNT	HRS	DATE	NAME	RATE	AMOUNT
	REFRIGERANT R- LBS.							
	FILTERS X X							
1	Trip Charge	50						
TOTAL MATERIALS				TOTAL LABOR				

Chris Pottin  
CUSTOMER SIGNATURE

8-8-22  
DATE

ATTACHMENT J-0200000-05  
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY 060 Schenectady Date of Visit: 8-8-22

Contractor Personnel on Site:

1. Mike D
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. NA
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_

Inspection, Testing, and Certification

1. NA
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_

Other Recurring Services

1. NA
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_

Service Calls - Service Call Number and Description

1. CSS # 18998 HP 224 HAS BAD FAN MOTOR
2. 8946 HP 223 HAS BAD FAN MOTOR
3. \_\_\_\_\_ HP 2-19 UNIT HAS ECM FAN MOTOR, ECM  
PROCESSOR BOARD IS FLASHING LED, NEED TO  
UNDERSTAND FLASH CODE.

ATTACHMENT J-0200000-05  
FORMS

**Over and Above Repair Work** – Order Number and Description of Work Completed

CSS# ~~10295~~ HP-2-24 HAS BAD FAN MOTOR  
8946 HP-2-23 HAS BAD FAN MOTOR  
HP-2-19 UNIT HAS ECM FAN MOTOR, ECM PROCESSOR  
BOARD IS FLASHING LED, NEED TO UNDERSTAND FLASH CODE.

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Mike Dull Date: 8-8-22  
Signed: M/Dull

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Chris Pothier Date: 8-8-22  
Signed: Chris Pothier

E-Mail: \_\_\_\_\_