

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
11/25/2022	1299-A

Name / Address
CMI Management 5285 Shawnee Road Suite #510 Alexandria, VA 22312

Project
123 Route 303 Orangeburg, NY 10962

CSS	Work Order	Terms
90744		Net 30

Item	Description	Qty	Rate	Total
Service	Remove and replace with new four RAB Occupancy Sensors in the main office and men's bathroom. Existing Occupancy Sensors malfunctioning. As per the Surge Protection Monitoring Equipment 46 power surges were detected at the center and could possibly be causing the Occupancy Sensors to be damaged. Due to these power surges, the new Occupancy Sensors cannot be warranted.	10	135.00	1,350.00
16 Electrical & Li...	Electrical material for above repairs.		700.00	700.00
Service	Diagnostics fee for above repair.		450.00	450.00
		Subtotal \$2,500.00		
		Sales Tax (8.875%) \$0.00		
		Total \$2,500.00		