

Fairview
Actuator

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: A 209 CSS Date of Visit: 2-6-19

Contractor Personnel on Site:

1. Ryan Himes
2. _____
3. _____
4. _____
5. _____
6. _____

Service Call Number

CSS# 16918 WO# 7113

Description of Repairs

REPLACED ACTUATOR MOTOR FOR 111-FLOOR HEAT AT MOTOR
PULL CHECKED OPERATIONAL

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Ryan Himes Date: 2-6-19

Signed: Ryan Himes

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: RICHARD ELLIOTT 65-09 Date: 2019/02/06

Signed: Richard Elliott

E-Mail: RICHARD.E.ELLIOTT49.GIV@MIL.MIL



ZONE 24 NC