



- ☐ Provide and install Spark Ignitor
- Provide and install Flame sensor
- Provide and install gasket channel
- Provide and install NIT burner
- Provide and install Burner door ceramic refractory
- Provide and install screw, washer, ceramic target wall
- Start up
- Warranty

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA051 Date of Visit: 12-19-18

Contractor Personnel on Site:

CSS# 16505-

- | | |
|------------------------|----------|
| 1. <u>Darren Young</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# _____ WO# _____

Description of Repairs

in Boiler 1 Munchkin Replaced front &
Rear Refractory with Proper Fasteners &
Gasket Replaced Ignitor & sensor with
main burner

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Darren Young Date: 12-19-18

Signed: Darren Young

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Joseph Knap WS09 Date: 19 Dec 2018

Signed: [Signature]

E-Mail: JOSEPH.KNAP.CIV@MAIL.MIL

