

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Proso

Date of Visit: 5/8/19

Contractor Personnel on Site:

1. Tony Gamm
2. Jim Gentry
3. Scott Wynn

4. Gary Betzel
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. 8523 8676
2. 8616 8736
3. 8764
4. 8546

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jim Gentry

Date: 5-8-19

Signed: _____

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Steven Davis GSgt

Date: 20190508

Signed: _____

E-Mail: _____

OTHER RECURRING SERVICES CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: P1080

Date of Visit: 5/8/19

Contractor Personnel on Site:

1. Tony Lazano
2. Jim Greengard
3. Scott Wynn

4. Gary Betz

5. _____
6. _____

Work Performed:

Other Recurring Services

1. GSPC

2. _____
3. _____
4. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jim Greengard

Date: 5-8-19

Signed: [Signature]

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Steven J. Davis GS#9

Date: 20190508

Signed: [Signature]

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST LIGHTING, OUTSIDE

SITE AND BLDG #:

PR 050-01

LOCATION/RM #:

MEP

WO# 0596

ASSET # 7467

MECHANIC

SIGNATURE:

DATE:

5/22/19

START TIME:

600

FINISH TIME:

C10

CHECK POINT	DESCRIPTION	TEST/COMPLETION		NOTES/ACTIONS
		YES	NO	
SPECIAL INSTRUCTIONS				
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.		/	
2	Schedule and coordinate work with operating personnel.	/		
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	/		
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Open and tag switch.	/		
2	Inspect visual condition of wiring. Look for evidence of overheating.	/		
3	Check for proper light operation.	/		
	Test operation of automatic switches/ time clock/ photocells if applicable.	/		
	Inspect light pole and mounting devices for deficiencies.	/		
	For any noted deficiency, takes pictures and open corrective maintenance ticket.	/		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.
To be performed by: General Maintenance Worker

Additional Notes:

6 R Double

Right hand outside of drill take out
Right hand on Right side of more Roll out