

## CERTIFICATION OF WORK PREVENTIVE MAINTENANCE

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA053-01 Date of Visit: 8/14/19

Contractor Personnel on Site:

1. Scott K
2. Dom S
3. \_\_\_\_\_
4. \_\_\_\_\_

### Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. W0 K 10247 FILTERS
2. 10337 FILTERS
3. 10419 ICE MACHINE, FRIDGE
4. WATER HEATERS
5. \_\_\_\_\_

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Scott Kenders Date: 8/14/19

Signed: Scott Kenders

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Al Mlynaruk Date: 8/14/19

Signed: Al Mlynaruk

E-Mail: \_\_\_\_\_

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

## Filter Replacement

SITE AND BLDG #: PA053

MECHANIC  
SIGNATURE:

57

LOCATION/RM #: 103

START TIME: 8:30 FINISH TIME: 8:48

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
	10337	4629-1	mmmmmm	Carrier				

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: GMW **Additional Notes:**

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

## Filter Replacement

SITE AND BLDG #: 9A053

MECHANIC  
SIGNATURE:  
*SK*

SK  
DATE: 8/14/19

LOCATION/RM #: 117

START TIME: 8:40

FINISH TIME: 8:50

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
	10337	4629-2	Ph-m042a Caster					

**Note:** The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: **GMW Additional Notes:**

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

## Filter Replacement

SITE AND BLDG #: PA053

MECHANIC  
SIGNATURE: *SK*

DATE:  
8/14/19

LOCATION/RM #: Lobby

START TIME: 850 FINISH TIME:

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
	10337	4629-3	Pm-mo4629	CAPPED				

**Note:** The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: GMW **Additional Notes:**