

SENTRY MECHANICAL



J.O. ✓
24 Hour Service

1724 Leechburg Road
Pittsburgh, PA 15235
Phone: 412-795-3040
Fax: 412-795-3204
Service Fax: 412-795-3206



INVOICE

SOLD TO CMI Management, Inc
c/o Bernard Koblinsky
939 Freeport Road
Natrona Heights, PA 15065

SHIP TO PA096 Washington Floor Drains
10 Scenic Drive
Washington, PA 15301-9211

| ACCOUNT NO | PO NUMBER | SHIP VIA | JOB NUMBER | TERMS | INVOICE DATE | PAGE |
|------------|-----------|----------|------------|--------|--------------|------|
| CMIM001 | CSS 15130 | | 193035TP | Net 30 | 7/15/2019 | 1 |

RE: CMI PA096 Drain Clogged

CSS 15130
WO 7535

Floor drain located in facility kitchen.

Re-route dishwasher drain line to floor drain next to the dishwasher. Floor drain currently routed to is corroded shut and can't get the snake past the trap.

| ITEM NO | QUANTITY | DESCRIPTION | UNIT PRICE | EXTENDED |
|-----------------|----------|--|------------|----------|
| PLUMBING SERVIC | 2:30 | *Initial Call* Plumbing Service Labor | 98.00 | 245.00 |
| PLUMBING SERVIC | 4:0 | Plumbing Service Labor | 98.00 | 392.00 |
| MATERIAL | 1:00 | Materials | 101.71 | 101.71 |

TOTAL AMOUNT **738.71**



Management, Inc.

Management, Inc located in facility kitchen has become clogged. When dishwasher is used, drains back up and cause water to accumulate on kitchen floor. Request is for vendor to clear all floor drains in both the kitchen AND mechanical room.

Proposal to provide and perform the following:

- Re-route dishwasher drain line to floor drain next to the dishwasher. Floor drain currently routed to is corroded shut and can't get the snake past the trap.



CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA 096 Date of Visit: 7-1-19

Contractor Personnel on Site:

1. _____ 2. _____

Work Performed: Run new 1/2" copper drain from the
dish washer to the floor drain

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment
identification, etc.)

1. WO# 7535

Service Calls - Service Call Number and Description

1. CSS# 15130

2. CSS# _____

3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Brian Martynovich Date: 7-1-19

Signed: Brian M

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the
best of my knowledge, completed the stated work listed:

Print Name/Rank: Hannah Florian GS-09 Date: 20190701

Signed: Hannah Fl

E-Mail: hannah.l.florian.civ@mail.mil









