

## Service Items


Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N
<b>TOTAL*:</b>	<b>\$0.00</b>				
* Not including taxes					

## Service Forms

Daily Form	Fill out every day, even on PMs, and projects
TECH NAME	Tom Timlin
DATE	3/28/23
POINT OF CONTACT:	Reginald
DESCRIPTION OF WORK PERFORMED	B-1 had a squealing noise coming from it. Found the inducer assembly with bearings going bad. Recommend replacing the inducer assembly. Boiler is still running at this time.
TOOLS USED	none
MATERIALS USED OR PICTURE OF TAG*	none
HOURS	REGULAR:
	OVERTIME:

## Attachments

Title	File Name
20230328_090915 03/28/2023 10:33 AM	ac31784b-47e9-41ce-a576-8ef1fc9358af.jpg



20230328_090924 03/28/2023 10:33 AM	cf827fcd-0c1e-4bb1-a1db-63787c9fdbff.jpg
--	--



## Service Items


Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N
<b>TOTAL*:</b>		<b>\$0.00</b>			

## **Service Forms**


<b>Daily Form</b>	Fill out every day, even on PMs, and projects
<b>TECH NAME</b>	Tom Timlin
<b>DATE</b>	6/12/23
<b>POINT OF CONTACT:</b>	Reginald
<b>DESCRIPTION OF WORK PERFORMED</b>	Removed the old bad inducer assembly out of boiler 2. Installed the new one with the new gaskets that come with it. Cycled the boiler and the inducer was working properly. Unit is running good at this time.
<b>TOOLS USED</b>	hand tools
<b>MATERIALS USED OR PICTURE OF TAG*</b>	1: inducer assembly (ordered)
<b>HOURS</b>	<b>REGULAR:</b> <b>OVERTIME:</b>

## Attachments

**Title** **File Name**  
20230612\_090015 c11936a3-b8d7-436e-b677-d415dffa4073.jpg  
06/12/2023 09:50 AM




20230612\_092321  
06/12/2023 09:50 AM




20230612\_092302  
06/12/2023 09:50 AM

fb0a41d9-cc55-4e0d-9312-d3a144493051.jpg



20230612\_090002  
06/12/2023 09:50 AM

56f77e6a-7cf7-4b7f-8f22-924c0702355c.jpg



20230612\_090005  
06/12/2023 09:50 AM

cbdf2679-4b93-4d6b-929f-d2b9cea15fbb.jpg



6-12-23 Meadville B-2  
inducer replacement

6-12-23 Meadville B-2 inducer replacement.pdf

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA062 Date of Visit: 3/28/23

Contractor Personnel on Site:

1. Tom Timlin 2. \_\_\_\_\_

**Work Performed:**

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. \_\_\_\_\_

**Service Calls** – Service Call Number and Description


1. CSS# 91050. HW actuator for offices
2. CSS# 92729. B-2 squeaking inducer assembly
3. CSS# \_\_\_\_\_

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Tom Timlin Date: 3/28/23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.  
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Rebecca Dithrich, GS-09 Date: 3/28/23

Signed: 

E-Mail: rebecca.l.dithrich.civ@army.mil

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA062 Date of Visit: 6/12/23

Contractor Personnel on Site:

1. Tom Timlin 2. \_\_\_\_\_

**Work Performed:**

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. \_\_\_\_\_

**Service Calls** – Service Call Number and Description


1. CSS# 92729. Install new inducer assmebly on B-2
2. CSS# \_\_\_\_\_
3. CSS# \_\_\_\_\_

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:


Print Name: Tom Timlin Date: 6/12/23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.  
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Rebecca Dithrich, GS-09 Date: 6/12/23

Signed: 

E-Mail: rebecca.l.dithrich.civ@army.mil