

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY030 Date of Visit: 7/25/2024

Contractor Personnel on Site:

1. <u>Keith Debolt</u>	4. _____
2. _____	5. _____
3. _____	6. _____

### Service Call Number

CSS# 98096 WO# 15822

### Description of Repairs

7/25/2024 Checked operation of the chiller. Compressor a on circuit one the breaker was tripped for the compressor. I reset the breaker and tested the operation of the compressor. The compressor is bad. I unwired the compressor and reset the breaker. Checked operation of circuit two. The fan cycling switch has been jumped out and is bad. There doesn't seem to be much of a load on the system at all. If you try to run more than one compressor at a time, the water temp drops too fast. Checked operation of the W 700 controller. Chiller temp is set at 50°. Do not advise lowering it any lower than that. I suspect that the evaporator is dirty and we are not getting good heat transfer. Also, I was not able to check the flow through the evaporator as there is no pressure gauges installed in the system. The chiller has three good operating compressors at this time.

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Julie Pape Date: 9/9/2024

Signed: Julie Pape

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata AFOS AFOS Date: 09/09/2024

Signed: John F. Granata

E-Mail: john.f.granata.ctr@army.mil

# POSTLER & JAECKLE

PLUMBING · HEATING · AIR CONDITIONING  
REFRIGERATION · SHEET METAL

24 HR EMERGENCY		1-800-724-4252	
NEW YORK OFFICES			
ROCHESTER	MAIN	585-546-7450	
	SERVICE	585-423-6214	
ALBANY	SERVICE	518-459-0910	
BINGHAMTON	SERVICE	607-757-0100	
SOUTHERN TIER	SERVICE	607-739-8303	
SYRACUSE	SERVICE	315-455-5587	
NEW JERSEY & PENNSYLVANIA		SERVICE	570-883-9563

**Customer** US ARMY CORPS OF ENGINEERS - HORSEHEADS (86823)

**Address** 3126 LAKE ROAD, HORSEHEADS NY 14845

**Contact** JOHN GRANATA/JODI (585-944-9099)

**Description** Q-TROUBLESHOOT CHILLER, CSS98096

## EQUIPMENT

Manufacturer	Model	Serial No.	Location	No.	Desc.	Parts Spec.
Trane	RAUCC40GPK03DFT	J95A80097				

## WORK PERFORMED

### Date Description

7/25/2024 Checked operation of the chiller. Compressor a on circuit one the breaker was tripped for the compressor. I reset the breaker and tested the operation of the compressor. The compressor is bad. I unwired the compressor and reset the breaker. Checked operation of circuit two. The fan cycling switch has been jumped out and is bad. There doesn't seem to be much of a load on the system at all. If you try to run more than one compressor at a time, the water temp drops too fast. Checked operation of the W 700 controller. Chiller temp is set at 50°. Do not advise lowering it any lower than that. I suspect that the evaporator is dirty and we are not getting good heat transfer. Also, I was not able to check the flow through the evaporator as there is no pressure gauges installed in the system. The chiller has three good operating compressors at this time.

## MATERIAL

Category	PO No.	Description

## LABOR

Date	Technician Name	Tech Id	ST	OT	DT	Shift	Remark
7/25/2024	Keith Debolt	91418	4.00				
		Total	4.00				

## TOOL RENTAL

Tool Description	Week Ending	M	T	W	T	F	S	S

## SUBCONTRACTOR

## RECOMMENDATION

<b>Job Status</b>	JOB STATUS COMPLETE	
<b>Accepted By</b>	Jodi	
<b>Tel</b>		Signature
<b>Email</b>	jodi.l.philipenko.civ@mail.mil	
<b>Comments</b>		Date
Note: tools and materials may not reflect those listed on the final invoice.		