

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VAO12 Dublin Date of Visit: 10/

Contractor Personnel on Site:

1. Dale Korth 2. Connor Pater

Work Performed: Replace started with OBM starter per quote.

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. Annual maintenance on Atlas Copco Oval Air Compressor  
changed air filter, checked B78 belts OK. Cleaned circumferential  
filter, changed compressor oil 1510  
Service Calls – Service Call Number and Description (Vanney Work order # 1510)

1. CSS# / WO# 98760

2. CSS#

3. CSS#

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Dale Korth Date: 10/8/24

Signed: Dale Korth

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed. This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Ssrhel, Daniel E, CIV Date: 10/8/24

Signed: Lt dA

E-Mail: daniel.e.ssrhel.civ@army.mil