

U.S. CRANE, INC.

CRANES, HOISTS: PARTS & SERVICE

(800) 466-8224 (513) 530-5252

DATE

8/29/2024

WORK ORDER #: 34203 - 40626

CUSTOMER: CMI MANAGEMENT, INC. (ARMY RESERVE)
6467 MIKE WOOD BLVD
CONNEAUT LAKE PA 16316

JOB CMI MANAGEMENT, INC. (ARMY RESERVE)
LOCATION: 6467 MIKE WOOD BLVD (PA118)
CONNEAUT LAKE PA 16316

CUSTOMER ORDER #: 4A-98872

CONTACT: REGINALD COOK
PHONE #: 703-738-5307

DATE REQUIRED: SEPTEMBER 2024

INITIAL DESCRIPTION OF PROBLEM OR REPAIRS TO BE DONE:

ANNUAL OSHA MAINTENANCE INSPECTION OF (1) OVERHEAD CRANE AND HOIST

U.S. ARMY RESERVE - CONNEAUT LAKE
REGION 4A - PA118

GARAGE - HIGH BAY, CR1
MONORAIL W/ HOIST & TROLLEY
SHAWBOX 10 TON

**MUST FILL OUT COW AND TAKE PICTURES OF ANYTHING FOUND
INCLUDES 26' SCISSOR LIFT TO AND FROM JOBSITE**

ABOVE COMPLETED: YES NO ALL PARTS USED: YES NO

DESCRIPTION OF ADDITIONAL WORK DONE AND PARTS USED :
IF ADDITIONAL WORK IS NOT RELATED TO ABOVE, A NEW WORK ORDER IS REQUIRED.

SERVICE AND PARTS STILL NEEDED:

CUSTOMER ACTION PRIORITY: HIGH MED LOW

INSPECTION LIST ON SERIAL #:

WIRE ROPE OR CHAIN CONDITION
 CHAIN OR CABLE CONNECTIONS
 ROPE REEVING
 HOIST HOOKS & LATCH
 LIMIT SWITCHES
 BRAKES

SLINGS
 PROPER OPERATION
 ALL FUNCTIONS
 WARNING DEVICES
 OVERALL CONDITION
 CONTROLS


P.B. STATION/CORD
 DISCONNECT SWITCH
 FESTOON SYSTEM


REMOVE FROM SERVICE:

YES NO

COMPLETE FUNCTIONAL TESTING OF ALL APPLICABLE ITEMS

SO # S-12391

TECHNICIAN SIGNATURE: 

CUSTOMER SIGNATURE: 

TODAY'S DATE: 9/25/24

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Garage High Bay Date of Visit: 9/25/24

Contractor Personnel on Site:

1. Snyder & Son's Electric 2. Brian Snyder
U.S. CRANE, INC.

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. Annual Crane Inspection

Service Calls – Service Call Number and Description

1. CSS# 4A - 98872 Inspection Job # 34203
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Brian Snyder Date: 9/25/24
Signed: Brian Snyder

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Mike Pennington Date: 9/25/24
Signed: Mike Pennington

E-Mail: _____