

TRI-STATE ROOFING & SHEET METAL COMPANY

P.O. Box 1231 Charleston, WV 25324 | (304) 755-8135, FAX (304) 755-5275 | Contractor Lic. # WV000104 | Website: www.tri-stateservicegroup.com

DATE 6-2-25 JUN 13 2025 **ROOFING WORK ORDER** JOB # 817178



I CUSTOMER CMI Management
N MFG JOB # FE MS # 3189925
V PO # WO# 19182
O ADDRESS _____
I CITY / STATE _____
C PHONE 703-738-5302
E CONTACT Reginald Cook
T CALL FOR APPT: ☐ No ☐ Yes

BLDG NAME US Army Reserve
W ROOF AREA(S) _____
O ADDRESS 101 Lakeview Drive
R CITY/STATE Cross Lanes WV
K CONTACT _____
A PHONE # (SITE) _____
T PHONE # (CELL) _____
 Emergency Response? _____

ROOF TYPE	<input type="checkbox"/> EPDM	<input type="checkbox"/> PVC	<input type="checkbox"/> TPO:	<input type="radio"/> Adhered	<input type="radio"/> Ballast	<input type="radio"/> M.A.S.	<input checked="" type="checkbox"/> METAL:	<input type="radio"/> S.S.	<input type="radio"/> Lap
	<input type="checkbox"/> BUR	<input type="checkbox"/> MOD-BIT:	<input type="radio"/> Gravel	<input type="radio"/> Smooth	<input type="radio"/> Granulated	<input type="checkbox"/> SHINGLE	<input type="checkbox"/> SLATE	<input type="checkbox"/> TILE	

Customer Description of Problem: Hazardous material storage building roof needs repaired after storm damage

Roof Service	ROOF DRAWING	DESCRIPTION OF REPAIRS/WORK PERFORMED
<input type="checkbox"/> Drains <input type="checkbox"/> Inspected <input type="checkbox"/> Cleaned <input type="checkbox"/> Gutter <input type="checkbox"/> Inspected <input type="checkbox"/> Cleaned <input type="checkbox"/> Downspout <input type="checkbox"/> Inspected <input type="checkbox"/> Cleaned <input checked="" type="checkbox"/> Field <input checked="" type="checkbox"/> Perimeter <input type="checkbox"/> Edge metal <input type="checkbox"/> Coving <input type="checkbox"/> Flashing <input type="checkbox"/> Wall <input type="checkbox"/> Curb <input type="checkbox"/> Cntr Flash <input type="checkbox"/> Wall <input type="checkbox"/> Curb <input type="checkbox"/> Ceiling Tile		<ul style="list-style-type: none"> Scraped and cleaned loose debris from roof Coated entire roof with Truco rubber roof coating Let Dry and re made 2nd Coat

QTY	MATERIAL DESCRIPTION	QTY	MATERIAL DESCRIPTION	QTY	MATERIAL DESCRIPTION
2 1/2	gal Truco coating				

SERVICE TECHNICIAN	WEATHER	TEMP	START DATE	FINISH DATE
Steve Facemyer	O	74°	6-5-25	6-5 6-11-25

WEATHER CODE: Sunny (S) Rain (R) Snow (SN) WINDY (W) OVERCAST (O) DRIZZLE (D) ICE (I)

TECH RECOMMENDATIONS: _____

- ☐ Billable T & M
☐ Manufacturer's Wty.
☐ Tri-State Wty.
- ☒ Work in Progress
☐ Complete

Mrs SSS CPL MATTHEW JULIAN
 Customer Signature

Tri-State Roofing & Sheet Metal will make repairs to localized areas that appear to be the source of leaks and will make a good faith effort to locate and try to stop leaks. Tri-State Roofing & Sheet Metal does not warrant that further leaks will not occur. Depending upon the condition, age and type of roof, future leaks may well be expected. Tri-State Roofing & Sheet Metal is not responsible for indoor air quality, interior or consequential damages, including mold, mildew, loss of use, damage to personal property, personal injury or claims from building occupants.

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Haz. mts. Date of Visit: 6-11-25

Contractor Personnel on Site:

1. Steve Faceyger 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. Cleaned and sealed with Truco rubber roof coating

Service Calls – Service Call Number and Description

1. CSS# / WO# 19182 Hazardous materials Storage bldg. Storm damage
2. CSS#
3. CSS#

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Steve Faceyger Date: 6-11-25

Signed: Steve Faceyger

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.

This is **NOT** a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: CPL MATTHEW JULIAN Date: 6-11-25

Signed: Ma

E-Mail: MATTHEW.JULIAN@USMC.MIL