



Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N

TOTAL*: \$0.00

* Not including taxes



Service Forms

Daily Form

Fill out every day. even on PMs, and projects

TECH NAME Mike opatt

DATE 5/16/25

POINT OF CONTACT: scott

DESCRIPTION OF WORK PERFORMED performed deep clean on mini split heads. put plastic around heads and sprayed with evap cleaner then rinsed with water and put units back in operation.

TOOLS USED hand

MATERIALS USED OR PICTURE OF TAG* 1 gallon of evap cleaner pic in attachment
2 cans of evap cleaner

HOURS REGULAR:
OVERTIME:






Attachments

Title

File Name

Kitchen After

029b493a-cd22-4506-ac5d-8a8252646a50.jpg



Kitchen before

659d9d61-fe21-40d2-878b-986a1bf39a8a.jpg


Out building after

bdb41642-aa79-4073-b6dc-0ca38a660f45.jpg




Out building

27ce0ec0-dc59-483d-b122-fe46202ff76e.jpg




Asset 5129 a

01be8154-1b16-4ebf-827c-88491d921db8.jpg




Asset 5129 b

8c4bc395-7793-4875-b819-844171a9183f.jpg



Asset 5129 a

c0a69cb7-2aff-4e86-bc4a-966c12eadb1f.jpg




Room 113 after

11884bca-c442-4a12-87de-2ebf1d22889c.jpg




Room 115 After

f7a26149-03a9-4af9-a01d-03d827c282c4.jpg




Asset 5128

c1387796-33b6-42ef-9543-1612e523f947.jpg




Asset5127

4eae52d5-24e1-40a9-add6-7e4cca851fb6.jpg




Asset 5127

faa7089d-7584-49e4-8844-bd331138b5ec.jpg




Asset 5129

6cfe169b-8d39-496e-a887-eac2a3d05e0a.jpg



Asset 5139

eaade5be-96d8-473a-a02a-ed81c13b8e47.jpg




Asset 5139

5b5a5e19-501c-445e-a5a9-ab323cfbf945.jpg



Asset 5127

cb650131-0eed-4a15-a230-93b37f716644.jpg




Asset 5128

78b59041-8e51-40d7-9479-ba7c2cf5e4c8.jpg



Evap cleaner

9b1a2abe-8ba3-4f71-be6b-d40551ccd11a.jpg




Asset 5139

a6754d11-3192-4790-84b2-c9aa5c857160.jpg



Room 113 before

09dcaa6f-cad4-46a2-a25a-6d8edc81a406.jpg




Room 118 after

2a278eae-1741-46f0-a1c5-158fad9636fe.jpg




106 before

89442e14-c154-4111-8a81-04316f94c114.jpg




115 before

caf4df18-261f-43e6-983c-9466b89c60f9.jpg




Room 118 indoor head

ff9e2742-2b9e-469d-85f3-94138a7fe075.jpg




Room 105 Before

c57c183a-d34d-482f-8d38-b9d8e5ac387c.jpg




Room 119 indoor head

faf0009d-9172-4c2a-a48b-bf083fad74c2.jpg




Room 104 Before

717509d0-d4c7-4cc8-96e1-81e167a72336.jpg




Room 118 Before

4f1a73d8-c893-4e31-9068-91bc85b2824e.jpg




Room 119 indoor head

d55c0177-9de2-4661-a35e-8473dd647670.jpg



Room 101 indoor head

eed255a1-a8a8-4b0c-bace-061fe4127b16.jpg




Room 101 indoor head

58afa58f-875f-4bbf-842e-cfb6118e1b4c.jpg




Room 101 indoor head

c14254cf-da58-44d5-9c50-7145775c04d7.jpg




Asset 5141

0ec08dc1-c2bf-4fe5-a666-46511a4ccd69.jpg




Asset 5141

904dd923-c018-4b6a-ab70-39163f9e0b60.jpg




Asset 5141

47635d98-6289-4680-a4b1-8532fa8b420b.jpg




Asset 5141

396c2912-b1f1-4381-943b-b2349cb8bd08.jpg




Asset 5126

791bbc10-8c88-4207-a2ff-1d807b09dc61.jpg




Asset 5126

d91af100-e094-4f47-8664-cc2c0dd9b841.jpg



Asset 5141

f770de5d-1813-4a5c-a233-b78028ec5e6f.jpg



Asset 5141

e520e9cc-a08d-4e2c-b78b-0c3aa35e1eed.jpg





Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N

TOTAL*: \$0.00

* Not including taxes



Service Forms

Daily Form Fill out every day, even on PMs, and projects

TECH NAME Jacob Powell

DATE 05-19-2025

POINT OF CONTACT: Reginald Cook

DESCRIPTION OF WORK PERFORMED deep cleaned the mini split indoor heads at franklin usarc.

TOOLS USED hand tools, vacuum

MATERIALS USED OR PICTURE OF TAG* 3- mini Split cleaning bags from shop
2- cans of evaporator coil cleaner from van stock

HOURS REGULAR:
OVERTIME:



Attachments

