

## Findings and Actions (1 Assets)

### 7.5 DEMAG

Single girder EOT - 1 trolley wire rope hoist

<b>Manufacturer</b>	DEMAG	<b>Span</b>	22ft
<b>Serial Number</b>	00398	<b>Lift</b>	18ft
<b>Criticality</b>	Moderate	<b>Volt/Ph/Hz</b>	480-3-60
<b>Capacity/SWL</b>	7 Ton	<b>Duty Class</b>	2m

**Service Products**      Planned Repairs

#### ✓ Single girder EOT - 1 trolley wire rope hoist

Repaired

**Date Reported:** Aug 3, 2018

**Technician:** Joshua Bioni

**Task Type:** Repair


**Fault Code:** Other fault

**Risk:** Safety Risk

**Recommendation:** Repair

**Comment:**

Arrived on site. Met with customer. Replaced all 4 bridge bumpers. Removed existing hoist geared limit switch. Installed new limit switch. Connected all wiring and set limits. Tested all functions and limits. All working properly.



---

Aug 3, 2018 Shawn McKay, Customer

---

Aug 3, 2018 Anthony Jeke, Technician