

(PRINTED BY THE CONTRACTOR AND SAVED IN THE CONTRACTOR'S CHAMPS)

FACID/Building: WV041

Date of Visit: 1/25/16

Contractor Personnel on Site:

1. Dale Doharich
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Service Call Number

CSS# 7116 WO# 6455

Description of Repairs

Replaced Motor Coupling on pump 1 - All operations ok +  
Replaced Phase Monitor on pump 2 - Found Bad  
Bearings in pump Motor - To be Quoted

#### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Dale Doharich Date: 1/26/19

Signed: Dale Doharich

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SGT JUN Daniel Date: 1/25/19

Signed: Dan





