

**Over and Above Repair Work – Order Number and Description of Work Completed**

SITE VISIT 3-4-19 (BUTLER PA.)  
CSS # 17108  
INSPECTED AREA'S AROUND BUILDING (GARAGE DOORS  
MULTIPLE STEEL ENTERANCE DOORS)  
   
   
 

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: CHRISTIAN MOORE / CUSTOM CONST. Date: 8-20-19

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Timothy S Peters Date: 20 AUG 2019

Signed:  

E-Mail: timothy.s.peters3.ctr@mail.mil

**CUSTOM CONSTRUCTION**  
**CHRIS MOORE**  
**103 SWEITZER RD.**  
**ACME PA.15610**  
**(724) 244-9438**

**INVOICE CSS # 17108**

**DATE: 8/18/19**  
**DATE OF SITE VISIT : 3/4/19**

**SUBMIT TO**

JOE BAYNE  
CMI

**LOCATION**

BUTLER USARC  
BUTLER PA.

**WORK PERFORMED**

SITE VISIT TO FACILITY  
ASSESS NEEDED REPAIRS TO MULTIPLE AREA'S AROUND FACILITY  
ESTIMATE LABOR COSTS  
ESTIMATE MATERIAL COSTS  
PROVIDED PROPOSAL

5.5 HRS./@ 80.00/HR.

**TOTAL DUE \$ 440.00**