

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: 95090 Date of Visit: 12/8/23

Contractor Personnel on Site:

1. **MidState Plumbing** 4. _____
2. _____ 5. _____
3. _____ 6. _____

Service Call Number

WO# 14266

Description of Repairs

~~Labor and material to a.) replace the recirculating pumps are steel which is causing rust build up in the hot water lines.
These pumps need to be switched to bronze pumps & flanges.~~

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Karlee Demain Date: 12/10/23

Signed: *Karlee Demain*

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Jennifer A Bailie Date: 12/19/2023

Signed: Jennifer A Bails

E-Mail: jennifer.a.bailie.ctr@army.mil