

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY051 BLDG1 Date of Visit: 2/8/22

Contractor Personnel on Site:

1. Patrick Brown 4. _____
2. _____ 5. _____
3. _____ 6. _____

Service Call Number


CSS# 34183 WO# 16285

Description of Repairs

when I got onto the roof I found the stack was rotted in several places, I removed the section of Stack that was leaning and a safety hazard and I temporarily mounted the cap on the pipe below to keep weather from getting inside the boiler there are four pieces of Stack that need to be replaced and the boot around the pipe on the roof was damaged and needs to be replaced. I also noticed when the stack fell over it damaged the intake pipe cap so that cap needs to be replaced too. I will submit a quote for repairs

To be signed by the Contractor:

Print Name: Patrick Brown Date: 2/8/22

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SFC ERIC ABBOTT Date: 2/8/22

Signed: 

E-Mail: _____

