

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY052 BLDG1 Date of Visit: 12/14/23

Contractor Personnel on Site:

1. <u>Patrick Brown</u>	4. _____
2. _____	5. _____
3. _____	6. _____

Service Call Number

CSS# 95165 WO# 14068

Description of Repairs

I removed the backflow that failed inspection
and reducing valve that was not functioning
properly and installed a new backflow and
reducing valve and tested for proper
operation

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 12/14/23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Travis McCall/SSC Date: 12/14/23

Signed: 

E-Mail: _____

