

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY070 Date of Visit: 10/8/2025

Contractor Personnel on Site:

1. Sean Phillips



Service Call Number

FEMS# 3366099 WO# 20297

Description of Repairs

Vehicle Maintenance Building panel shows Trouble for 1st Fl Women's Rest Room 116 Audible/Visual - No Answer.

Troubleshooting revealed missing 10k Ohm resistor missing from end of Strobe Circuit. Installed resistor and Trouble cleared.

Main Building panel was System Normal at the time of this visit but showed in History that 2nd Fl Mech Rm 227 Duct Detector was Excessively Dirty on 10/5/25.

Detector head removed, cleaned, and reinstalled. At time of departure, both panels show System Normal.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: SEAN PHILLIPS Date: 10/8/2025

Signed: Sean Phillips

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata AFOS Date: 10/16/2025

Signed: John F. Granata

E-Mail: john.f.granata.ctr@army.mil