

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

INSPECTION, TESTING, AND CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY030, NY070, NY126 Date of Visit: _____

Contractor Personnel on Site:

1. _____	4. _____
2. _____	5. _____
3. _____	6. _____

Work Performed:

Inspection, Testing, and Certification

1. NY030 WO 8891 Asset 6572 WO 8892 Asset 6574 WO 8893 Asset 6576
2. WO 8894 Asset 6577 WO 8895 Asset 6656
3. NY070 WO 8930 Asset 6588 WO 8931 Asset 6605 ~~WO8926 Asset 6587~~ ~~WO8927 Asset 6604~~
~~WO8928 Asset 6615~~ ~~WO8929 Asset 6622~~
4. NY126 WO 8852 Asset 6529 WO 8853 Asset 6530

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Timothy R Houk Date: 07/09/2019

Signed: Timothy R Houk

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata AFOS Date: 7/9/19

Signed: John F. Granata

E-Mail: john.f.granata.ctr@mail.mil



OneCIS Insurance Company

95 Oakwood Rd
Lake Zurich, IL 60047
(855) 593-5115
www.us.bureauveritas.com

WO 8852 Asset 6529
WO 8853 Asset 6530

7/2/2019

44110-007210.00

Chili US Army Reseve Center
49 Jetview Dr
Rochester, NY 14624-4903

RE: Jurisdictional Inspection:
Chili US Army Reseve Center
49 Jetview Dr
Rochester, NY 14624-4903

Thank you for the consideration I received during my visit on 5-20-19 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by John Granata Area Facility Operations Specialist, 585-944-9099, during my visit.

The inspections were performed on behalf of Tidewater, Inc. (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
2011	Water Tube	111752	111752	None
2011	Water Tube	111681	111681	None
2012	Water Tube	8113	8113	None

The following observations were noted during the inspection of this equipment: the boilers and the boiler room were in good working order.

As a result of these inspections 0 recommendations were suggested.

Based upon this visit, OneCIS Operating Certificates for each boiler are being created and forwarded to the client.

The next inspection is tentatively scheduled to be completed by 05/20/2020.

Please contact me by phone at 724-396-5433 or by e-mail at joseph.klages@bureauveritas.com if there are any questions and to clear any recommendations.

Sincerely,

joseph.w.klages

DISTRIBUTION

Cc:

Tidewater Inc.
Adam Colopy
3761 Attucks Dr
Powell, OH 43065-6080
adam.colopy@tideh2o.net