

*By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified time line:

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

Building: VA099-01 _____ Date of Visit: 6/14/19

Contractor Personnel on Site:

1. Trey CRAIG 2. _____

Work Performed:

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders -

PM/SO	WO #	Asset #	PM #	Asset Description
	8870	2367	FQ-2371	J-1502000-08 3-pc Fan Coil
	8870	2371	FQ-2371	J-1502000-15 1-pc Mini Split Indoor Unit 3 Ton
	8870	2372	FQ-2371	J-1502000-15 2-pc Mini Split 2 Ton
	8870	2373	FQ-2371	J-1502000-15 1-pc Mini Split 3.5 Ton
	8870	2374	FQ-2371	J-1502000-15 1-pc Mini Split 1.5 Ton
	8870	2375	FQ-2371	J-1502000-15 1-pc Mini Split 2 Ton
	8870	2376	FQ-2371	J-1502000-15 1-pc Mini Split 1.5 Ton
	8903	1423	PM-AN-1425	J-1502000-07 4-pc Transfer Fan
	8903	1424	PM-AN-1425	J-1502000-07 6-pc Exhaust Fan
	8903	1425	PM-AN-1425	J-1502000-07 1-pc Kitchen Exhaust Fan
	8903	1426	PM-AN-1425	J-1502000-07 2-pc Kitchen Exhaust Fan
	8904	1435	PM-AN-1435	J-1502000-55 1-pc Arms Vault Rm 17
	8921	1465	PM-MO-1465	J-1502000-49 1-pc Automatic Gate 2013 Sgl Gate,Auto,Cantilever Road to motor pool
	8948	1672	PM-QT-1672	J-1502000-12 2-pc Chill Water Pump 132GPM,75ft
	8948	1673	PM-QT-1672	J-1502000-12 2-pc Hot Water Pump 55GPM,45ft
	8955	2367	PM-SA-1672FC	J-1502000-08 3-pc Fan Coil

CERTIFICATION OF WORK

*By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified time line:

To be signed by the Contractor:

Print Name: 11204 CRAIG Date: 6/14/19

Signed: 

To be signed by Facility Manager:

Print Name/Rank: DONALD HINSON Date: _____

Signed: 

E-Mail: _____