

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY126 bldg 2 Date of Visit: 3/20/19

Contractor Personnel on Site:

1. Patrick Brown 4. \_\_\_\_\_  
2. \_\_\_\_\_ 5. \_\_\_\_\_  
3. \_\_\_\_\_ 6. \_\_\_\_\_

**Service Call Number**

  CSS# 16697 WO# 6843

**Description of Repairs**

I found cord from cord reel, going to safety edge ,wrapped up in the shaft. and bottom of door operator ripped apart I remove the cord from the Shaft and took apart the cord reel and fixed the connections and checked all wiring inside door opener panel and repaired bottom of opener. Also I did a complete PM on the door - Asset# 7789 ..... cord reel should be replaced it is functioning at this time but I feel the connections are going to burn out inside the reel.....

**CERTIFICATION OF WORK**

To be signed by the Contractor:


Print Name: Patrick Brown Date: 3/20/19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John Granata Date: 3/20/19

Signed: 

E-Mail: \_\_\_\_\_

