

#12353
#12224

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE002

Date of Visit: 2/27/2019

Contractor Personnel on Site:

1. GREGG VHOE
2. CHRIS HARMON
3. _____
4. _____
5. _____
6. _____

Service Call Number

CSS# 12399 WO# 6878 and 6436

Description of Repairs

Disconnected linesets & electric from old booster; removed old booster. Installed new booster header, connected linesets and electric & turned unit and water on. Leak checked. Filled unit & ran through operations. Heating element operational

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: CHRIS HARMON Date: 2/27/2019

Signed: CHris HARMON

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Castellanos, Hector G/659 Date: 2019 Feb 27

Signed: Hector G. Castellanos

E-Mail: hector.g.castellanos-a/cantara.civ@mail.mil







