

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA 027 Date of Visit: 11/27/18

Contractor Personnel on Site:

1. <u>Eric Busa</u>	4. _____
2. _____	5. _____
3. _____	6. _____

Service Call Number

CSS# 15813 WO# 5929

Description of Repairs

I replaced the ignition module and control module on boiler #6612. This is the munchkin

Boiler second from the right I also rewired the control module on boiler #6620

This is the first boiler on the far right. pictures will show before and after repairs

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Eric Busa Date: 11/27/18

Signed: _____

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Shadowens, Gary Date: 27 NOV 18

Signed: _____

Digitally signed by SHADOWENS,GARY.LEE.1091739590
Date: 2018.11.27 14:58:19 -05'00'
Location: C:\Program Files\Microsoft\Aladdin\LLC\1091739590
Date: 2018.11.27 14:58:19 -05'00'

E-Mail: _____



**RENICK
BROTHERS**
Mechanical Contractors



Renick Brothers
<http://www.renickbrothers.com/>
PO Box 94
Slippery Rock, PA 16057
724-794-4200
wbecker@renickbrothers.com

WORK ORDER REPORT



Customer #168

Display name Tidewater
Customer Type Commercial
Custom Id 168
Company name Tidewater
Pricing Tier Tier 1
Description \$ 450.00 Min Bill. without Quote



Map data ©2018 Google



Service : USARC Farrell : 950 Sharon New Castle Road, Farrell, PA 16121, United States

Address Type Service
Street address 950 Sharon New Castle Road
Apt/Suite
City, State ZIP Farrell, PA 16121, United States
Description
Contact **Phone** 740-819-6207 **Type** –Not Set–
 Adam Coliday



Service Request #56703

Summary Repairs to boilers at USARC Farrell parts received 11-26
Date Requested 11/09/2018
Description Repairs to Boiler, from Inspectors report. repair wiring to boiler, and restart system. check operation
Created 11/09/2018 01:37 PM
Customer Tidewater



Work Order #56703-3

Description Repairs to boilers at USARC Farrell parts received 11-26
Technician Eric Busa
Status Complete
Start 11/27/2018 01:00 PM
End 11/27/2018 04:00 PM
Invoicing Memo

Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached page for details of work performed.	\$0.00	Hour	1	N
TOTAL*:	\$0.00				

* Not including taxes



Service Forms

Daily Form

tech name: Eric Busa
materials used: 7250P-713
munchkin control replacement
description of work performed: I replaced the control module and start module on the second boiler from the right and repaired the control module on the boiler all the way on the right.
HOURS: REGULAR:
OVERTIME:



Attachments

Title

20181127_144341
11/27/2018 02:56 PM

File Name

f8dea413-bb6f-416a-ab5c-83d6817ff260.jpg




Gary Shadowence
11/27/2018 03:01 PM

cbf15017-d99d-421c-8893-311ac35e1f7b.png


Signature is acceptance of Service provided

11/27/2018 02:57 PM

20181115_085009
11/27/2018 02:56 PM 5e3dd729-4b82-4721-a9c2-302eb88cdecf.jpg



20181127_144352
11/27/2018 02:56 PM 58bdaa40-dab7-4a9a-9576-e8f6324bfc4d.jpg



20181115_085018
11/27/2018 02:56 PM faa3809b-5526-425b-a751-fca963c1b4fc.jpg

