

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA027 Date of Visit: 12/20/18

Contractor Personnel on Site:

- | | |
|---------------------|----------|
| 1. <u>Eric Busa</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 16164 WO# 6404


Description of Repairs

I Trouble shot The #1 AHU unit on the roof.
I discovered that The unit was down because of blown
fuses in the unit 120 control circuit. The fuses being
blown where because of a burnt out Condenser fan motor.
I replaced the fuses and disabled the Condenser fan motor for now.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Eric Busa Date: 12/20/18

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SHADOWENS, GARY Date: 12/20/18

Signed: 

E-Mail: _____

1075
0
5.4
E INS
SEMI-ENCL.
NORMALLY PROTECTED
TH 15.0 MFD 370 VAC
CA 15.0
ASSEMBLED IN MEXICO
P85460

VOLTS 208-230
TYPE UF
1
AMB 40°C
AIR OVER DUTY

SP®

BROWN
WHITE
BLACK

614129 614131-004

