

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039- Bldg 1 <sup>Army</sup> side Date of Visit: 2-1-19

Contractor Personnel on Site:

1. HYDE-STONE
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Service Call Number

CSS# 16891 WO# 2004

### Description of Repairs

CHANGED FLAME IGNITER AND INSPECTED  
THE PILOT AND WATCHED THE BOILER RUN AND  
ALL LOOKS GOOD

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: DEREK PERRY Date: 2/1/19

Signed: [Signature]

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Douglas Rushton Date: 2/1/19

Signed: [Signature]

E-Mail: douglas.rushton.cdr@mail.mil

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039 - Bldg 1 A Side Date of Visit: 1-4-19

Contractor Personnel on Site:

1. Patrick Brown
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Service Call Number

CSS# 16891 WO# 2004


Description of Repairs

Replaced U.V. Flame Sensor On Boiler #1 Asset #9902

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 1-4-19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: GYSgt Richard Cabaya Date: 2018-01-4

Signed: 

E-Mail: Richard.Cabaya@usmc.mil







