

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY039 - Bldg 1 Date of Visit: 2-14-19

Contractor Personnel on Site:

1. Patrick Brown
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

Service Call Number

CSS# 17187 WO# 2504

### Description of Repairs

Removed old corroded and leaking pipes and  
Replaced them with new 1" copper Pipe & Fittings, connected  
to a dielectric union screwed to Black Pipe with a new  
3/4" Boiler drain valve at the bottom

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 2-14-19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Douglas Rushko Date: 02-14-19

Signed: 

E-Mail: douglas.rushko.cvr@mail.mil





300UK54  
Copper Drain Valve, 3/4  
in., MPT x GHT