

Additional Funding Request

MD002	CSS# 17606 WO# 7578 Asset# NA															
Description of Repairs	Labor and materials to repair various doors throughout building #1.															
Diagnosis: Initial Work Order	There are multiple doors throughout building #1 that are in need of repair. The door from the assembly area into the kitchen has a handle that continuously falls off and cannot be secured. The double doors from the assembly area into the supply entrance needs adjustment. The exterior door in the supply entrance needs the hinges repaired (they have been adjusted multiple times in the past and the issue persists). The right door from the main hallway into the caging area has part of the hardware ripped off and needs to be repaired in order to secure the space properly.															
Diagnostic Fee	<p>\$160.00</p> <p>TW Labor \$80/hr x 2</p>															
Additional Labor Cost to Perform Repairs	<p>\$ 320.00</p> <p>TW Labor \$80/hr x 4</p>															
Additional Material Cost to Perform Repairs	<p>\$ 454.38</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">#1RM24 Manual Hydraulic Norton 7500 Series Door Closer, Heavy Duty Interior and Exterior, Aluminum</td> <td style="width: 10%;">1</td> <td style="width: 10%;">\$253.72</td> <td style="width: 10%;">\$253.72</td> </tr> <tr> <td>#52AU17 4-1/2" x 2-1/4" Butt Hinge Square Corners</td> <td>6</td> <td>\$29.55</td> <td>\$177.30</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$23.36</td> </tr> </table>				#1RM24 Manual Hydraulic Norton 7500 Series Door Closer, Heavy Duty Interior and Exterior, Aluminum	1	\$253.72	\$253.72	#52AU17 4-1/2" x 2-1/4" Butt Hinge Square Corners	6	\$29.55	\$177.30	Sales Tax			\$23.36
#1RM24 Manual Hydraulic Norton 7500 Series Door Closer, Heavy Duty Interior and Exterior, Aluminum	1	\$253.72	\$253.72													
#52AU17 4-1/2" x 2-1/4" Butt Hinge Square Corners	6	\$29.55	\$177.30													
Sales Tax			\$23.36													
Total Cost of Repair	\$ 934.38															



WORK ESTIMATE

CSS #:

17606

Work Order #:

7578

Emergency

Urgent

Routine

CM

Company Name:	Tidewater, Inc.	Facility ID:	DE001
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	adam.colopy@tideh2o.net	Classroom/Room #)	
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT


Labor and materials to repair various doors throughout building #1.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			4	\$320.00
#1RM24 Manual Hydraulic Norton 7500 Series Door Closer, Heavy Duty Interior and Exterior, Aluminum	1	\$253.72		\$253.72
#52AU17 4-1/2" x 2-1/4" Butt Hinge Square Corners	6	\$29.55		\$177.30
Sales Tax				\$23.36
Diagnostic			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$454.38	Labor \$480.00
			TOTAL	\$934.38

2 Products in Johnny's MD002

The product(s) selection below has been provided to you for your shopping convenience from a Shared List so that you may easily add item(s) to your cart for purchase.

 Select All

Item	Price	Qty	Total Price
<input type="checkbox"/>  Manual Hydraulic Norton 7500-Series Door Closer, Heavy Duty Interior and Exterior, Aluminum Item #: 1RM24	Web Price <small>1</small> \$211.60 / each	<input type="text" value="1"/>	\$211.60
<input type="checkbox"/>  4-1/2" x 2-1/4" Butt Hinge with Dull Stainless Steel Finish, Full Mortise Mounting, Square Corners Item #: 52AU17	Web Price <small>1</small> \$24.62 / each	<input type="text" value="6"/>	\$147.72

List Total Price \$359.32 Select All









