

Region: 5

Location: DE002

CSS #: 18183

Maximo Work Order No.: 8399

Asset #: NA

Date Issued: 4/16/19

Original Description: We need a CSS# and ticket opened to again access to EMS to trouble shoot drill hall heating controls

Repairs Needed:

Existing BAS is inaccessible; provide (1) day to access and troubleshoot existing system. Provide comprehensive report to END User identifying any/all BAS deficiencies.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
1	NA	Vehicle Charge	--	--	\$48.00	--	\$48.00
2	NA	Corordination and Oversite	4	\$80.00	--	--	\$320.00
--	NA	Labor	16	\$150.00	--	--	\$2,400.00
1	NA	Sales tax					\$146.88

Estimate Summary:

Labor Hours	Labor Cost	TAX	Vehicle	Total Cost	CE Factor	Total Estimate
20	\$2,720.00	\$146.88	\$48.00	\$2,914.88	102%	\$2,973.18

