

## Additional Funding Request

<b>DE002</b>	<b>CSS# 18852 WO# 8808 Asset# 1724</b>															
Description of Repairs	Labor and materials to repair defective safety edge on overhead door.															
Diagnosis: Initial Work Order	The safety sensor on the middle overhead door is not working and needs to be repaired. This causes a safety concern if left as is.															
Diagnostic Fee	<p>\$ 160.00</p> <p>TW Labor \$80/hr x 2</p>															
Additional Labor Cost to Perform Repairs	<p>\$ 480.00</p> <p>TW Labor \$80/hr x 6</p>															
Additional Material Cost to Perform Repairs	<p>\$ 735.78</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">17' of Miller electric safety edge</td> <td style="width: 10%;">1</td> <td style="width: 15%;">\$39.82</td> <td style="width: 25%;">\$676.94</td> </tr> <tr> <td>Freight</td> <td>1</td> <td></td> <td>\$30.00</td> </tr> <tr> <td>Sales Tax</td> <td>1</td> <td></td> <td>\$33.84</td> </tr> </table>				17' of Miller electric safety edge	1	\$39.82	\$676.94	Freight	1		\$30.00	Sales Tax	1		\$33.84
17' of Miller electric safety edge	1	\$39.82	\$676.94													
Freight	1		\$30.00													
Sales Tax	1		\$33.84													
Total Cost of Repair	\$ 1,375.78															



# WORK ESTIMATE

CSS #:

18852

Work Order #:

8808

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.	Facility ID:	DE002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>	Classroom/Room #)	
Assigned Technician(s):	John Brown		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to repair defective safety edge on overhead door..

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
17 Feet Miller electric safety edge	17	\$39.82		\$676.94
Sales Tax				\$33.84
Freight				\$25.00
Diagnostic			2	\$160.00
SUB-TOTAL COSTS:	Materials Total	\$735.78	Labor	\$640.00
			TOTAL	\$1,375.78



3501 Century Avenue Baltimore, Maryland 21227

Date: April 25, 2019

Order #: N/A

Bill to: Tidewater, Inc.

Job site: Elkridge, Md.

Attn: John Brown

Door location: N/A

**PROPOSAL**

THE OVERHEAD DOOR COMPANY OF BALTIMORE, INC. is pleased to propose the following:

We will furnish only for pick up 1 Miller electric safety edge, 16'2" in length per customer.

Please keep in mind that we will have to send a truck to the site to get our own specs for the safety edge so the correct edge is ordered. No charge for this if it is within 1/2 hour of our shop (21227).

Thank you.

17' @ \$33.18' = \$564.06  
Tax - \$33.84  
Freight - \$25.00

**Total Price \$ 622.90**

Should you have any questions concerning this proposal, please do not hesitate to contact me directly.

Very truly yours,

A handwritten signature in blue ink that reads "Jim Zepp".

Jim Zepp

OVERHEAD DOOR CO. of BALTIMORE, INC.

Phone: 410-636-6306 ext. 317@ FAX: 410-789-1053. E-MAIL: jzepp@ohdbalt.com

X \_\_\_\_\_ Date: \_\_\_\_\_ P.O.# \_\_\_\_\_

50% Deposit required if C.O.D.


Print Name Please

Standard warranty –  
Labor 30 days

No warranty –  
Labor 0 days

All parts –  
1 year warranty

Quote is valid for 90 days. Please allow approximately \_\_\_\_\_ days for delivery of required parts.



SENNHEISER  
SINGING EDGE  
WST CROWN RAY

