

Additional Funding Request

MD002	CSS# 19695 WO# 10127 Asset# NA
Description of Repairs	Labor to remove and dispose of broken counter/shelf in first floor Men's Restroom. Will Repair/Patch/Paint wall to match.
Diagnosis: Initial Work Order	Building 1, male latrine on 1st floor has a broken shelf in front of the mirrors. Remove shelf, repair wall and paint to match.
Diagnostic Cost	\$ 0
Additional Labor Cost to Perform Repairs	\$ 640 TW – 8hrs @ \$80/hr
Additional Material Cost to Perform Repairs	\$ 0
Total Cost of Repair	\$ 640



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.		Facility ID:	MD002
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207		Building/Location: (e.g., Classroom/Room #)	Men's Restroom 1st Floor
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	John Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor to remove and dispose of broken counter/shelf in first floor Men's Restroom. Will Repair/Patch/Paint wall to match.

