

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY067 BLDG1 Date of Visit: 7/25 - 7/26/19

Contractor Personnel on Site:

1. <u>RFC CONTRACTING INC</u>	4. _____
2. <u>Patrick Brown</u>	5. _____
3. <u>ART ADLER</u>	6. _____

Service Call Number

CSS# 20245 WO# 5048


Description of Repairs

water jetted west and east main sewer lines outside and snaked
out west and east lines inside the building and replaced 4 caps.

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Art Adler Date: 7/26/19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Ammie Mearero Date: 7/26/19

Signed: 

E-Mail: _____

